Owner Name and Address: Warrens Welcome Stop Inc Highway 2 PO Box 32 Bainville MT 59212 Phone: (406) 769-2000

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4313761	The Welcome Stop	US Highway 2	Bainville	59212	(406) 769-2000
		PO Box 32			

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / S3 Currently In Use	3387	12/1/1997 08 / Ye	Diesel 10,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	ABCDEFGHIJ&L B DEFOHIJKL	Yes Yes Yes Yes
4 / S4 Currently In Use	3388	12/1/1997 08 / Ye	Gasoline 10,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	(ABCDEFGHIJEL B DEFOHIJEL	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 1 of 17

Owner Name and Address: Robert Nygard PO Box 248 Brockton MT 59213 Phone: (406) 786-3229

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4302099	B & S Quick Stop	US Highway 2 & 7th St	Brockton	59213	(406) 786-3237
		PO Box 248			

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 06 Currently in Use	1828	6/12/1995 11 / No	Gasoline 7,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	ABCDEFOHIJKL B DEFGHIOKL	Yes Yes Yes Yes
2 / 07 Currently in Use	1829	6/12/1995 11 / No	Gasoline 5,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	ABCDEF®HIJKL B DEFGHI®KL	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 2 of 17

Owner Name and Address: Cenex Harvest States PO Box 56 Brockton MT 59213 Phone: (406) 786-3221

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
4313651	Cenex Harvest States Brockton Elevator	600 S Tracks Road	Brockton	59213	(406) 786-3221	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	4317	1/1/1983 23 / No	Diesel 20,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	8 DEF@HIJKL	Yes Yes Yes Yes
2 / 02 Currently in Use	4318	1/1/1983 23 / No	Gasoline 20,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	B DEEBHIJKT	Yes Yes Yes Yes
3 / 03 Currently In Use	4319	8/1/1999 06 / No	Diesel 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABC●EFGH() ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( )	Yes Yes Yes Yes
4 / 04 Currently In Use	4320	8/1/1999 06 / No	Diesel 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABC • EFGH   J & L B D E F • H   J & L	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 3 of 17

Owner Name and Address: Oelkers Inc PO Box 272 Culbertson MT 59218 Phone: (406) 787-5315

Sys Fac I	Location Name	Location Street Address	<b>Location City</b>	Zip	Location Phone
4300030	Oelkers Service Center	4 E 6th St	Culbertson	59218	(406) 787-5315

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	1774	1/10/1953 53 / No	Gasoline 3,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Safe Suction	(ABCOEFGHIJKL B DEFGHIOKL	Yes Yes Yes Yes
2 / 02 Currently in Use	1775	1/10/1953 53 / No	Diesel 3,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Safe Suction	B DEFGHIOKL	Yes Yes Yes Yes
3 / 03 Currently in Use	1776	1/10/1953 53 / No	Gasoline 3,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Safe Suction	ABCOEFGHIJKL B DEFGHIOKL	Yes Yes Yes Yes
4 / 04 Currently in Use	1777	1/10/1953 53 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Safe Suction	ABCOEFGHIJKL B DEFGHIOKL	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 4 of 17

Owner Name and Address: Douglas & Tammie McCormick 148 Glenhaven Dr Billings MT 59105 Phone:

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
4301991	Val Am Stop N Shop	110 W 6th St N	Culbertson	59218	(406) 787-6380	_

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
5 / 05 Currently in Use	3517	7/1/1990 16 / No	Gasoline 6,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	ABCDEF.H.J.K.L B.DEF.G.H.J.K.L	No Yes Yes Yes
6 / 06 Currently in Use	3518	7/1/1990 16 / No	Diesel 6,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	ABCDEF.H.I.J.K.L. B.DEF.G.H.I.O.K.L.	No Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 5 of 17

Owner Name and Address: Missouri Breaks Purvis Truck Stop 515 6th St E PO Box 690 Culbertson MT 59218 Phone: (406) 787-6200

Inc

Sys Fac I	Location Name	Location Street Address	<b>Location City</b>	Zip	Location Phone
4303015	Missouri Breaks Truck Stop	515 6th St E	Culbertson	59218	(406) 787-6200

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Temporarily Out of U		5/5/1978 28 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Bare Steel Impressed Current	Safe Suction	ABCD®F@HIJKL B DEF@HI®KL	Yes Yes Yes Yes
2 / 02 Temporarily Out of U		5/5/1978 28 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Bare Steel Impressed Current	Safe Suction	<b>B D E F G H J K L</b>	Yes Yes Yes Yes
3 / 03 Temporarily Out of U		5/5/1978 28 / No	Diesel 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Bare Steel Impressed Current	Safe Suction	8 DEFGH10KL	Yes Yes Yes Yes
4 / 04 Temporarily Out of U		5/5/1978 28 / No	Diesel 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Bare Steel Impressed Current	Safe Suction	ABCD®F@HJJ&L B DEF@HJ®KL	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 6 of 17

Owner Name and Address: Miller Oil Co Inc PO Box 408 Culbertson MT 59218 Phone: (406) 787-6271

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
4307758	Triple M Sinclair	3rd W & 6th St	Culbertson	59218	(406) 787-6271	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	3635	7/1/1985 21 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABCOEFGHIJKL  OEFGHIJKL</pre>	Yes Yes Yes Yes
2 / 02 Currently in Use	3636	7/1/1985 21 / No	Diesel 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL  • • EFGHIJKL	Yes Yes Yes Yes
4 / 04 Currently in Use	3637	7/1/1985 21 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL  • • EFGHIJKL	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 7 of 17

Owner Name and Address: Farmers Union Oil Co 105 2nd Ave N PO Box 68 Froid MT 59226 Phone: (406) 766-2339

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4304415	Farmers Union Oil Co Froid	105 2nd Ave N	Froid	59226	(406) 766-2339

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
6 / 06 Currently in Use	958	10/1/1990 15 / No	Diesel 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	(ABC●EFGHIJKL B DEFGHI●KL	Yes Yes Yes Yes
7 / 07 Currently in Use	959	10/1/1990 15 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	(ABCOEFGHIJKL B DEFGHIOKL	Yes Yes Yes Yes
8 / 08 Currently in Use	960	10/1/1990 15 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	(ABCOEFGHIJKL B DEFGHIOKL	Yes Yes Yes Yes
9 / 09 Currently in Use	961	10/1/1990 15 / No	Diesel 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	(ABC • E F G H 1 J K L) (B D E F G H 1 • K L)	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 8 of 17

Owner Name and Address: Butchs Exxon PO Box 987 Poplar MT 59255 Phone: (406) 768-3651

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4301508	Butchs Exxon Service	400 F Ave W	Poplar	59255	(406) 768-3651

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 08 Currently in Use	508	1/1/1991 15 / No	Gasoline 4,000	Cathodically Protected Steel Double-Walled	Bare Steel Impressed Current	U.S. Suction	<b>⊗ B C B E F G H 1 J K L</b>	Yes Yes Yes Yes
4 / 09 Currently in Use	509	1/1/1991 15 / No	Gasoline 4,000	Cathodically Protected Steel Double-Walled	Bare Steel Impressed Current	U.S. Suction	<b>ABCDEF®HJJK</b> L <b>● DEF</b> GHJJKL	Yes Yes Yes Yes
10 / 10 Currently in Use	510	1/1/1991 15 / No	Diesel 4,000	Cathodically Protected Steel Double-Walled	Bare Steel Impressed Current	U.S. Suction	ABCDEF. HIJKL  • DEF. HIJKL	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 9 of 17

Owner Name and Address: Tom Atkinson 302 F St PO Box 6 Poplar MT 59255 Phone: (406) 768-3371

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4302100	TJs Quick Stop	302 F St	Poplar	59255	(406) 768-5225

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 03 Currently In Use	<b>0</b> 8/	/1/1996 09 / No	Gasoline 7,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCDEF•H1J&L B DEF•H1J&L	No Yes Yes Yes
4 / 04 Currently In Use	<b>0</b> 8/	/1/1996 09 / No	Gasoline 5,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCDEF.H).J.K.L B DEF.H).J.K.L	No Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 10 of 17

Owner Name and Address: Farmers Union Oil Co Wolfpoint 60 US Highway 2 E Wolf Point MT 59201 Phone: (406) 653-1510

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4310278	Farmers Union Oil Co Poplar	US Highway 2 E	 Poplar	59255	(406) 768-3251

TankiD/Alt TankiD Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 05 Currently in Use	997	6/1/1994 12 / No	Diesel 10,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	ABC●EFGHIJ&L B ●EF●HIJ&L	Yes Yes Yes Yes
2 / 06 Currently in Use	998	6/1/1994 12 / No	Diesel 10,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	B	Yes Yes Yes Yes
3 / 01 Currently in Use	993	10/27/1984 21 / No	Diesel 10,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized		Yes Yes Yes Yes
4 / 04 Currently in Use	996	6/1/1994 12 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B OEFOHIJKL	Yes Yes Yes Yes
5 / 02 Currently in Use	994	10/27/1984 21 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<b>ABC</b> ● <b>EFGH1JKL</b> <b>B</b> ● <b>EFOH1JKL</b>	Yes Yes Yes Yes
6 / 03 Currently in Use	995	10/27/1984 21 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B OEFOHIJKL	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 11 of 17

Owner Name and Address: Fort Peck Assiniboine & Sioux PO Box 1027 Poplar MT 59255 Phone: (406) 768-5155

Tribes

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4313620	Tribal Express	US Highway 2 E	Poplar	59255	(406) 768-5450

TankID/Alt TankID Status	1 •   ====	stalled e/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	10/1/ 13		Gasoline 10,000	Cathodically Protected Steel Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	ABC • E F G H 1 J K L  B • E F • H 1 J K L	Yes Yes Yes Yes
2 / 02 Currently in Use	10/1/ <sup>-</sup> 13		Gasoline 6,000	Cathodically Protected Steel Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<b>ABC⊕EFGHJ%L</b> <b>B ●EF●HJJ%L</b>	Yes Yes Yes Yes
3 / 03 Currently in Use	10/1/ <sup>-</sup> 13		Gasoline 6,000	Cathodically Protected Steel Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	ABCOEFGHJ&L B OEFOHJ&L	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 12 of 17

Owner Name and Address: City of Wolf Point 201 4th Ave S Wolf Point MT 59201 Phone: (406) 653-1852

Sys Fac I	Location Name	Location Street Address	<b>Location City</b>	Zip	<b>Location Phone</b>	
4300843	L M Clayton Airport	MT Highway 13	Wolf Point	59201	(406) 653-2250	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
5 / 06 Currently in Use	648	11/1/1992 13 / No	Other 8,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	ABCDEFOHIJKL B DEFGHIOKL	Yes Yes Yes Yes
6 / 07 Currently in Use	649	11/1/1992 13 / No	Other 4,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	(ABCDEF®HIJKL B DEFGHI®KL	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	Not Listed

Report Generation Date: 7/3/2006 Page 13 of 17

Owner Name and Address: Farmers Union Oil Co Wolfpoint 60 US Highway 2 E Wolf Point MT 59201 Phone: (406) 653-1510

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
4306866	Farmers Union Oil Co Westside Station	60 US Highway 2 E	Wolf Point	59201	(406) 653-1510	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
7 / 07 Currently in Use	4327	6/1/1994 12 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHJJKL  • • EFGHJJKL	Yes Yes Yes Yes
8 / 08 Currently in Use	988	6/1/1994 12 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<pre></pre>	Yes Yes Yes Yes
9 / 09 Currently in Use	4328	6/1/1994 12 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHJJKL  • • • • • • • • • • • • • • • • • • •	Yes Yes Yes Yes
10 / 10 Currently in Use	990	6/1/1994 12 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHJJ&L  • • • • • • • • • • • • • • • • • • •	Yes Yes Yes Yes
11 / 11 Currently in Use	4329	6/1/1994 12 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHJJ&L  • • • • • • • • • • • • • • • • • • •	Yes Yes Yes Yes
12 / 12 Currently in Use	992	6/1/1994 12 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHJJ&L • • • • • • • • • • • • • • • • • • •	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 14 of 17

Owner Name and Address: Clifford & Nora Hagadone 529 4th Ave S Wolf Point MT 59201 Phone: (406) 653-1357

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
4308029	Clifford & Nora Hagadone	529 4th Ave S	 Wolf Point	59201	_	

TankID/Alt TankID Tag Status Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Temporarily Out of Use	4/14/1976 30 / No	Used Oil 8,000	Asphalt Coated or Bare Steel None	No Piping None	Not Listed	ABCDEFGHIJKD  B DEFGHIJKL	No Yes Yes No

## **Tank/Piping Release Detection Codes**

A Manual Tank Gauging C Invent	tory Control E Vapor Monit	toring G Interstit, Dbl-Wall Monitor	I SIR	K Deferred	
	,	9		L Not Listed	

Report Generation Date: 7/3/2006 Page 15 of 17

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4308725	Town Pump Inc Wolf Point	401 Cascade St	Wolf Point	59201	(406) 653-3206

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	4774	4/14/1985 21 / No	Gasoline 12,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	(ABC ) E F G H ( ) K L B ( ) E F G H ( ) K L	Yes Yes Yes Yes
2 / 02 Currently in Use	4775	4/14/1985 21 / No	Gasoline 12,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	B	Yes Yes Yes Yes
3 / 03 Currently in Use	4776	4/14/1985 21 / No	Gasoline 12,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	(ABCOEFGH)JKL B OEFGH)JKL	Yes Yes Yes Yes
4 / 04 Currently in Use	4777	4/14/1986 20 / No	Diesel 6,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJKL B OEFOHIJKL	Yes Yes Yes Yes
5 / 05 Currently in Use	4778	4/14/1986 20 / No	Diesel 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJKL B OEFOHIJKL	Yes Yes Yes Yes
6 / 06 Currently in Use	4779	6/28/2002 04 / No	Diesel 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOHIJKL B OEFOHIJKL	Yes Yes Yes Yes

## **Tank/Piping Release Detection Codes**

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 16 of 17

Owner Name and Address: Farmers Union Oil Co Wolfpoint 60 US Highway 2 E Wolf Point MT 59201 Phone: (406) 653-1510

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
4310279	Farmers Union Oil Co Wolf Point	60 US Highway 2 E	 Wolf Point	59201	(406) 653-1510	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C	
9 / 09 Currently in Use	999	8/1/1996 09 / No	Diesel 30,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B OEFOHIJKL	Yes Yes Yes Yes	
10 / 10 Currently in Use	1000	8/1/1996 09 / No	Gasoline 30,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	B	Yes Yes Yes Yes	
11 / 11 Currently in Use	1001	8/1/1996 09 / No	Gasoline 20,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B OEFOHIJKL	Yes Yes Yes Yes	
12 / 12 Currently in Use	1002	8/1/1996 09 / No	Gasoline 6,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B OEFOHIJKL	Yes Yes Yes Yes	
13 / 13 Currently in Use	1003	8/1/1996 09 / No	Gasoline 14,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B OEFOHIJKL	Yes Yes Yes Yes	
14 / 14 Currently in Use	1004	8/1/1996 09 / No	Diesel 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B OEFOHIJKL	Yes Yes Yes Yes	
15 / 15 Currently in Use	1005	8/1/1996 09 / No	Diesel 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B OEFOHIJKL	Yes Yes Yes Yes	

## **Tank/Piping Release Detection Codes**

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 17 of 17